



## Clarity Devitrification Solution

- Clean glass as usual
- Do not stir or shake bottle before application
- Using a foam brush or sprayer, lightly coat surface & sides of the top piece of glass only
- Do not allow the coating to migrate between or underneath the glass
- Allow to dry completely before moving to the kiln
- Only use water to remove the coating
- Wash brushes with clear water to clean
- Do not ingest and avoid contact with eyes
- Working temperatures around 1350F—1500F

Clarity contains no toxic or harmful chemicals. However, caution should always be used when applying any solution.

10-1-2019

